

# Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program Sanitary Sewer Overflow (SSO)/Bypass Notification Form

FOR DEP USE	ONLY
Tax Identification	Number

# A. Reporting Facility

1.	Facility Information				
Hull, MA WPCF			MA0101231		
Reporting Sewer Authority		<del></del>	Permit #		
2.	Authorized Representat	ive Transmitti	ng Form:		
Ara	am		Varjabedian	781-925-0906	
Fir	st Name		Last Name	Telephone No.	
Pla Tit	ant Manager			avarjabedian@woodardcurran.com E-mail Address	
111	ie .			E-mail Address	
В.	Phone Notifications	s:			
1.	MassDEP staff contacte Contacted By	d: Email	David First Name	Burns Last Name	
2.	Date/Time contacted: Contacted by: EPA staff contacted:		02/26/2018 10:48 AM David	– Turin	
	Contacted by:	Email	First Name	Last Name	
	Date/Time EPA contac	ted:	02/26/2018 10:48 AM	-	
3.	Board of Health contacted Contacted by:	ed: Email	Joyce First Name	Sullivan Last Name	
	Date/Time contacted:		02/26/2018 10:48 AM	_	
4.	Others notified:	Joyce,Hu Manager		ornheim,Division of Marine Fisheries - Ryan ahforst,DPW Director - Jim Dow,Town	
			ary SSO notification by email to a		
	COMMINE	IIIO FIGIIIIIII	in y 000 Houndation by email to a	an.	



# Massachusetts Department of Environmental Protection

Bureau of Resource Protection – Watershed Permitting Program

# Sanitary Sewer Overflow (SSO)/Bypass Notification Form

C.	C. 550 Information				
1.	SSO Discovered:				
	By: James Dinapoli		Date and Time 0	1/25/2018 01:50 PM	
2.	SSO Stopped Date and Tim	ate and Time02/25/2018 05:00 PM [approx time]			
3.	SSO Discharge from:	Backup into Property			
	Sanitary Manhole, Pump Station, Backup into property, Other - Specify Below				
Specify: Back up into homeowners shower, reported by Jim Dinapoli [homeowner]					
4.	4. SSO Discharge to: Backup into Property [contained within home]  Ground Surface, Direct to Receiving Water, Catch Basin to Receiving Water, Backup into Basement				
	Specify:				
L	ocation: 36 J Stree	et, Hull, Ma			
	X,Y Coordinates 42.29626		scription of discharge site	e or closest address)	
	Estimated SSO Volume at t		Based upon homeowne	ers shower stall basin and spilla	age over it.
Method of Estimating Volume:			Other Specified Below		
					The beautiful and the second of the second o
		Homeowner estimate and shower sump capacity. The homeowner was not home after the system surcharge was pumped down, so the actual time that the			
			E	SO back-up was stopped is esti	
6	Cause of SSO Event:	Sewer System Blockage			
Ο.		ent, PS Failure, Insufficient Capacity in System, Treatme	ent Unit failure , Sewer System Blockage, F	Pipe Collapse, Root Intrusion, Grease Blockage, Othe	97
	Specify:				
		Inspection of all area sewers in	dicated blockage. Follow	wed collection system manhols	es towards the nump
		station and found last manhole			
		next upstream manhole and for			
7.	. Corrective Actions : the next downstream manhole				
		site. The vactor truck jetted and had to be cleaned due to rag as			
		were inspected again and found			and the second s
	Impact Area cleaned and/o	or disinfected: Yes	Cor	rrective Actions Completed:	Yes
		No outside area impacted, but	homeowner has initially	cleaned their shower and adia	cent area, and is co-
	Details:	ordinating with a clean up comp			



# **Massachusetts Department of Environmental Protection**

Bureau of Resource Protection – Watershed Permitting Program

# Sanitary Sewer Overflow (SSO)/Bypass

# **Notification Form**

## D. Comments/Attachments/Follow-up


Additional comments and planned actions:


None planned at this time.


I wish to provide the following:


Attachement, Additional Comments

Attachement, Additional Comments, No Additional Comments or Attachements











#### Massachusetts Department of Environmental Protection

Bureau of Resource Protection - Watershed Permitting Program

# Sanitary Sewer Overflow (SSO)/Bypass

#### **Notification Form**

#### E. Certification Statement

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature of Authorized Representative Date Signed

Please keep a copy of this report for your records. When submitting additional information, include the MassDEP Incident Number from

### MassDEP Regional Office and EPA Telephone and Fax Numbers:

Northeast Phone: 978-694-3215 Fax: 978-694-3499 Southeast Phone: 508-946-2750 508-947-6557 Fax: Central Re Phone: 508-792-7650 Fax: 508-792-7621 Western F Phone: 413-784-1100 Fax: 413-784-1149 EPA Cont. Phone: 617-918-1870 Fax: 617-918-0870 DEP 24-h(Phone: 888-304-1133

# **Town of Hull Wastewater Treatment Plant**

1111 Nantasket Avenue Hull, MA 02045 (781) 925-1207




NPDES Permit # MA0101231

# Unauthorized Discharge Summary to Surface Waters 36 L Street [2-25-18]

No Release to MS4, ground, wetland, or surface water


Location (address or latitude and longitude);	On SSO form
Date and Time unauthorized discharge began;	On SSO form
Date and Time unauthorized discharge stopped;	On SSO form
Source of the notification (e.g., property owner, field crew, police);	Property owner was the source – notified the "On-Call" pager.
Type of asset from which the unauthorized discharge occurred (e.g., station, manhole, main);	Manhole was blocked causing back up.
Estimated gallons released;	estimate <25 gallons
Method used to estimate volume;	Discussion with homeowner and shower stall dimension. Calculated volume.
Cause of the unauthorized discharge, (blockage or break; mechanical, electrical, or structural failures);	Blockage in sewer line at MH 20290 on L Street near house # 34.
If caused by a blockage, identify the type of blockage (e.g., grease, rags, debris);	Rags, rocks, debris found
If caused by a mechanical, electrical, or structural failure, the date of the last inspection, maintenance, or repair of the failed asset;	NA NA
Did the release reach any portion of the Town's Municipal Separate Storm Sewer System ("MS4").	No release to MS4

If the release occurred to the ground, provide the location of the nearest down-gradient catch basin and the name of the receiving water to which the catch basin discharges;	No release to ground
Did the release reach a wetland or surface water? If so, include the name and exact location where?	No release
Measures taken to minimize the volume and duration of the unauthorized discharge;	See corrective action on SSO form
Measures taken to clean the area where the unauthorized discharge occurred;	Homeowner to contact cleaning company to clean affected area in home, per the Sewer Dept.
Corrective actions taken to prevent reoccurrence of unauthorized discharges at the same location;	Sewer line jetted and vacuumed out debris from manholes
Date of the last unauthorized discharge in the same general location;	Unknown




2/25/18 - Inspected ALL Manholes for blockage + backed up flow

ALL flow from this area flows to MH 20290 + then to PS 6.










36 I Street Homeowner Shower pictures

In background is

from in playground by busted to the Where jething + 4+ ctoring done MH 20283

> bloc hage Suisnes Sindab MACHERING OUT MH 20290

After cleaning MH 20296





+ 1000 77698


La broughtuld past bleacher in

420 88502 HM

where blockage was. Street @ 34 L Street

In buckground is









overview of Area - 36 I street in relation to playground.

## **Aram Varjabedian**

From:

Aram Varjabedian

Sent:

Monday, February 26, 2018 10:48 AM

To:

Berardinelli, Terri; Bill Boornazian; david.burns (david.burns@state.ma.us); Dow, James (jdow@town.hull.ma.us); Frank Cavaleri; jstruzziery (jstruzziery@town.hull.ma.us); jsullivan (jsullivan@town.hull.ma.us); Kate Roosa (kroosa@woodardcurran.com); kbornheim (kbornheim@town.hull.ma.us); Krahforst, Chris (ckrahforst@town.hull.ma.us);

Confinent (kbomineim@town.nuii.ma.us), kramoist, Chris (ckramoist@town.nuii.m

Lemnios, Philip (plemnios@town.hull.ma.us); O'Connor, Carol; Robert Scott

(rscott@woodardcurran.com); Turin, David (Turin.David@epa.gov)

Subject: Attachments: RE: Hull, MA - MA0101231 - Preliminary Notification of SSO - 36 L Street, Hull, MA

20180226\_104017\_resized.jpg

Tracking:

Recipient Delivery Read

Berardinelli, Terri

Bill Boornazian Delivered: 2/26/2018 10:48 AM

david.burns

(david.burns@state.ma.us)

Dow, James

(jdow@town.hull.ma.us)

Frank Cavaleri

Delivered: 2/26/2018 10:48 AM

Read: 2/26/2018 10:51 AM

jstruzziery

(jstruzziery@town.hull.ma.us)

jsullivan (jsullivan@town.hull.ma.us)

Kate Roosa

Delivered: 2/26/2018 10:48 AM

(kroosa@woodardcurran.com)

kbornheim

(kbornheim@town.hull.ma.us)

Krahforst, Chris

(ckrahforst@town.hull.ma.us)

Lemnios, Philip

(plemnios@town.hull.ma.us)

O'Connor, Carol

Robert Scott

Delivered: 2/26/2018 10:48 AM

(rscott@woodardcurran.com)

Turin, David (Turin.David@epa.gov)

#### Good morning:

I am emailing to inform you that a sewer line blockage on "L" Street in Hull near #34 L Street and adjacent to the playground/PS 6, caused a back-up in the gravity sewer system for that area and affected the #36 "J" Street residence, where sewage backed up into the homeowner's shower. At this time, the preliminary estimated volume is less than 25 gallons into the home, most of which was contained mostly to the shower basin.

The call from homeowner at 36 J Street came in at 1:53pm yesterday, and staff was dispatched to inspect the "J" Street area. Manholes were found to be surcharged and the investigation widened to include Central Ave and "L" Street manholes, and these were also surcharged. All of the sewer lines flow towards the playground and Pump Station #6. The manhole near #34 L Street was

surcharged, and the next downstream manhole towards the pump station and in the playground near the basketball court was dry with no flow.

A number of calls were made for contractor assistance between 3pm and 4pm, with National Water Main Co. available and quickest to respond. In the interim, since no response heard back yet on pump trucks, a 4-inch portable trash pump was set up to pump the surcharged sewage to the dry manhole. The pump was set up and operational for approximately 2 hours. The level of surcharged sewage was greatly reduced by the time that the jet/vac truck arrived at approximately 615pm.

Both pumps at PS 6 eventually clogged and had to be cleaned. This was done while the blockage and jetting of lines were cleared. Accumulated rags were removed from the pumps as well as collected in the vactor truck [approx. 0.5 yds of material].

To date, no additional calls have been made to report any additional issues in this area. All area manholes were rechecked after the problem was resolved last evening.

A full report will be filed in the next couple of days. Should you have any questions, please call me at 781-925-0906.

Sincerely,

#### Aram

Aram Varjabedian
Plant Manager
Hull Wastewater Treatment Facility
1111 Nantasket Avenue |Hull, MA 02045
Phone 781.925.0906 | Fax 781.925.3056 | Cell 339.214.8334
www.woodardcurran.com

